

ELECTRICAL DESIGN GROUP

ELECTRICAL BUILDING SERVICES CONSULTANTS
P.O. Box 15, SHERWOOD Q. 4075

Phone: (07) 3278 4375

Website: www.edg.net.au Email: brisbane@edg.net.au

C3599a - TI-TREE COLLECTIVE DISTRIBUTION BOARD DB-2 REVISION A - 14 OCTOBER 2025

C3599a-0008(A).xls

| | | | | | | | REV |
|--|----|----------------|------------------|--------------|----------------|-----------------------------|-----|
| | | FAULT CURRENT: | 6KA | | MAIN SWITCH: | 100A NON AUTO LOAD BREAK | Α |
| | | CHASSIS SIZE: | 30 POLE | | SUPPLIED FROM: | MSB | Α |
| CHASSIS RATING: | | | 250A | | SUPPLY CABLE: | 4C+E 16 | Α |
| | | PHASES: | 3 | | | | Α |
| REFER TO THE POWER SCHEMATIC FOR DETAILS OF CIRCUITS P1 AND P2. PROVIDE THE DB WITH SURGE PROTECTION. REFER TO THE NOTES FOR ADDITIONAL REQUIREMENTS | | | | | | | |
| CIRC | PH | CIRCUIT | CONTROL | CABLE | LOCATION | CIRCUIT | Α |
| | | BREAKER (amps) | EQUIPMENT | SIZE (mm²) | | USE | Α |
| P3 | 1 | 32 | RCBO | 6.0 | KITCHEN | COOK TOP | Α |
| P4 | 3 | 32 | RCBO | 6.0 | LAUNDRY | HWS | Α |
| P5 | 1 | 20 | RCBO | 2.5 | KITCHEN | OVEN | Α |
| P6 | 1 | 20 | RCBO | 2.5 | | GPO | Α |
| P7 | 1 | 20 | RCBO | 2.5 | | GPO | Α |
| P8 | 1 | 20 | RCBO | 2.5 | | GPO | Α |
| P9 | 1 | 20 | RCBO | 2.5 | | GPO | Α |
| P10 | 1 | 20 | RCBO | 2.5 | | GPO | Α |
| P11 | 1 | 20 | RCBO | 2.5 | | GPO | Α |
| | | | | | · | | Α |
| | | | | | | | Α |
| L1 | 1 | 20 | RCBO | 2.5 | | LIGHTS | Α |
| L2 | 1 | 20 | RCBO | 2.5 | | LIGHTS | Α |
| L3 | 1 | 20 | RCBO | 2.5 | | LIGHTS | Α |
| | | | | | | | Α |